Inspections conducted 10 days apart with driver operating on a class C in a class A CDL required vehicle.

Unit Type				<u>Eq</u>	uipmen	LID VIN GVWR CVSA # Issued # OOS Sticker
1 TR F	FORD 2	022 TX			4309	6489 14000
2 ST	TXP 2	024 TN			2	1 303 17600
BRAKE A	JUST	MENTS				
<u>Axle #</u>	1	2	<u>3</u>	<u>4</u>		
Right	N/A	N/A	N/A	N/A		
Left	N/A	N/A	N/A	N/A		
Chamber	HYDR	HYDR	ELEC	ELEC		
VIOLATIO	NS					
		<u>nit OOS</u>	Citation :			Violations Discovered
383.23A2	FC) Y		N		Operating a CMV without a CDL: Operating a CMV without a CDL on 7/21/2024. None -
						driver only has class C license out of Texas - Driver stated that the trailer has been d- rated but has no docum
391.41A1-	F) Y		N		Derating a property-carrying vehicle without possessing a valid medical certificate.
FPC						Previously Cited on [DATE]: 7/11/24 report Finance and the second
						a medical card at this time
395.8A-	FC	Y C		Ν		ELD - No record of duty status (ELD Required): No Log on 7/21/2024. Driver stopped on
ELD						7/11/24 and needed an ELD at this time, driver stated he has one but its not working -
200 OFT						has not notified carrier, FMCSA
392.2FT	FC	D N		N		State or International Fuel Tax (IFTA) Violation: No fuel permits or IFTA for Kansas (K- TRIPS.ORG to get permit)
396.17C	F 1	I N		N		Operating a CMV without proof of a periodic inspection: None - driver has a Texas inspection
000.110						nowever does not comply with 396.17
393.95A	F 1	I N		N		No/discharged/unsecured fire extinguisher: Not secured, in bed of truck - driver is aware it
						has to be secured
392.2IRP	F 1	I N		N		RP Apportioned Tag or Registration Violation: No Kansas registration (only has Texas) K-
200 000	- /			N		TRIPS.ORG to obtain permit
396.9D2	F	I N		N	N	Failure to correct defects noted on previous inspection report: Inspection report for annual inspection
396.17C	F 2	2 N		N	N	Operating a CMV without proof of a periodic inspection: None - Has a Texas inspection (good
000.000						for Texas) does not comply with 396.17
393.43	F 2	2 Y		U		No/improper breakaway or emergency braking: Not connected to the power unit at all,
					j	ust laying in the bed of the pickup
396.9D2	F 2	2 N		Ν	N	Failure to correct defects noted on previous inspection report: Inspection report for annual inspection
	N 41 11	aneous				Placard: Yes Cargo Tank:

VEHICLE IDE							
<u>Unit</u> Type Mak				<u>Plate</u> Eq	uipmer	<u>nt ID</u>	VIN GVWR CVSA # Issued # OOS Sticker
1 TR FOR	D 2022	2 T)	<		4309		489 14000
2 ST OTH	R 2024	1 TN	1		2		303 17600
BRAKE ADJU	STME	INTS	:No b	orake mea	sureme	ents	required for level II or level III
VIOLATIONS							
Section	Type	<u>Unit</u>	<u>00S</u>	Citation #	Verify C	Crash	Violations Discovered
391.41A	F	D	N		N	Ν	NO MEDICAL CERTIFICATE ON PERSON (CARD) (FMCSR 391.41(a)): NONE
393.205C	F	2	Ν		Ν		WHEEL FASTENER LOOSE/MISSING (FMCSR 393.205(c)): 1 MISSING AXLE 3 LEFT
395.8A-ELD	F	D	Y		Ν		ELD - NO RECORD OF DUTY STATUS (ELD REQUIRED) (FMCSR 395.8(a)(1)): 3RD INTERSTATE TRIP THIS MONTH NO RECORD FOR ANY TRIP
396.17C	F	1	Ν		Ν	Ν	OPERATING A CMV WITHOUT PROOF OF PERIODIC INSPECTION (INSPECTION CERTIFICATE RECEIPT) (FMCSR 396.17(c)); NO ANNUAL TRUCK
396.17C	F	2	Ν		Ν	Ν	OPERATING A CMV WITHOUT PROOF OF PERIODIC INSPECTION (INSPECTION
392.2C	F	D	Ν		Ν	Ν	CERTIFICATE RECEIPT) (FMCSR 396.17(c)): NO ANNUAL TRAILER DISREGARD OFFICIAL TRAFFIC CONTROL DEVICE: RAN SCALE - LIGHTS ON. STOPPED AT TRACTOR SUPPLY AND BR
			ted				Placard: Cargo Tank:

_			In Si In	tart: 12:36 PM	e: 03/22/2024 ICT End:12 el: II - Walk-A	2:54 PM CT round
USDOT# MC/MX# State#:	Phone#: Fax#:		river: icense ate of oDriver: icense#: ate of Birth:	:		State: TX State:
Location Highway: County:		MilePost: Origin: Destin	Shippe	er: SELF Bill of Ladi Cargo: RO	ing: 4410773 CK	
Highway:		Origin	Shippe	Bill of Lad		
Highway: County:		Origin		Bill of Lad	CK	<u>A # 005#</u>
Highway: County: VEHICLE IDENTIFICATION		Origin: Destin	960	Bill of Lad Cargo: RO	CK	<u>A # 005#</u>
Highway: County: VEHICLE IDENTIFICATION Unit Type Make Year State 1 TT INTL 1999 TX	Plate # Eq	Origin: Destin uipment ID VIN 512	960	Bill of Ladi Cargo: RO <u>GVWR</u> <u>CVS</u> 52,350	CK	3A# <u>OOS#</u>
Highway: County: VEHICLE IDENTIFICATION Unit Type Make Year State 1 TT INTL 1999 TX 2 ST OTHR 2017 TX	Plate # Eq	Origin: Destin uipment ID VIN 512	960	Bill of Ladi Cargo: RO <u>GVWR</u> <u>CVS</u> 52,350	CK	<u>A# 005#</u>

These two inspections were conducted 24 hours apart the inspector stated it was apparent the violations had been present for an extended period of time.

						Report Number: Inspection Date: 0 Start: 1:08 PM CT Inspection Level: HM Inspection Typ	End:01:31 PM CT I - Full
USDOT#: MC/MX#: 000000 State#	000 Fax#			Lic Da Co Lic	ver enser: te of Bi Driver: ense#: te of Birt	h:	State: TX State:
Location Highway: County:			MilePc Origin Destination:		Ship	per: Bill of Lading: Cargo: EMPT	
VEHICLE IDEN Unit Type Make 1 TT INTL 2 ST BRAZ BRAKE ADJUS	Year State Plate # 1999 TX 2017 TX	Equip 51	ment ID2	VIN	960)46	<u>GVWR</u> <u>CVSA #</u> 52,000 70,000	New CVSA # OOS#
Axle # Right1 1 LeftLeft1 ChamberChamberC-20	2 <u>3</u> 1 1/4 1 1/2 1 1/2 2	<u>4</u> <u>5</u> 1 1 1/4 1 1 1/2 C-30 C-30					
VIOLATIONS							
Vio Code 396.3A1BL	Section 396.3A1BL	<u>Unit</u> <u>OO</u> 1 Y	S Citation #	Verify A	Crash N		ered DSS RATE (FMCSR PED BELOW 60PSI AND
396.3A1B	396.3A1B	1 Y		Α	N	AUDIBLE AIR LEAN	K AT AIR CHAMBER (FMCSR HEN SERVICE BRAKE
393.75A3	393.75A3	1 Y		Α	N		R INFLATED (FMCSR
393.100A	393.100A	2 Y		А	N	NO PROTECTION A	AGAINST SHIFTING/FALLING 93.100(a)): ROCKS FELL OFF
393.55D3	393.55D3	2 N		N	N	NO OR DEFECTIVE INDICATOR FOR TO VEHICLES MANUF	ABS MALFUNCTION OWED VEHICLES ON ACTURED AFTER MCSR 393.55(d)(3)):
393.95A	393.95A	1 N		Ν	Ν		ER VIOLATION (FMCSR CURE BETWEEN SEATS
393.47A	393.47A	1 N		N	N	BRAKES NOT MAIN WORKING ORDER	ITAINED IN GOOD (GENERAL) (FMCSR DSE JAM NOT, NOT
393.11TU	393.11TU	1 N		Ν	Ν	REQUIREMENTS F SHEETING OR REF MATERIAL (MANUF	UPPER BODY CORNER OR RETROREFLECTIVE FLEX REFLECTIVE FACTURED >6/97) (FMCSR OFF/ PARTS MISSING
393.11TL	393.11TL	1 N		Ν	Ν	TRUCK-TRACTOR	LOWER REAR

Inspection 7/10/24 (2 pages violations), inspections about 1 month apart and drastically different results. Both inspections were marked as level II inspections.

VEHICLE IDENT						
Unit <u>Type</u> <u>Make</u> 1 TT PTRB 2		<u>Ec</u>	uipment ID 24	VIN	757	<u>GVWR</u> <u>CVSA #</u> <u>New CVSA #</u> <u>OOS#</u> 52,000
	022 TX		24		119	80,000
BRAKE ADJUST Axle # 1 Right 1 Left 1 Chamber C-24	MENTS					
VIOLATIONS Vio Code	Section	Unit	OOS Citation #	Verify	Crash	Violations Discovered
393.75A3	393.75A3	2	Y	B	N	TIRE-FLAT / UNDER INFLATED (FMCSR 393.75(a)(3)): A4R INNER 22/110PSI
396.3A1-TC	396.3A1-TC	2	Y	В	N	TIRE IN CONTACT WITH ANOTHER PART OF THE VEHICLE (FMCSR 396.3(a)(1)): A5R OUTER BULDGE INNER WAL TOUCHING INSIE TIRE
393.95A	393.95A	1	Ν	Ν	Ν	FIRE EXTINGUISHER VIOLATION (FMCSR 393.95(a)): NOT SECURE IN CAB
393.78	393.78	1	Ν	Ν	Ν	WINDSHIELD WASHING SYSTEM (FMCSR 393.78): NO FLUID
393.100A	393.100A	2	Y	В	N	NO PROTECTION AGAINST SHIFTING/FALLING CARGO (FMCSR 393.100(a)): ASPHALT ON REAR LEDGE ABLE TO FALL OFF
393.9	393.9	1	Ν	Ν	Ν	INOPERABLE/OBSCURED ID LAMP (FMCSR 393.9): REAR LEFT ON TRAILER INOP
393.11TU	393.11TU	1	Ν	Ν	N	TRUCK-TRACTOR UPPER BODY CORNER REQUIREMENTS FOR RETROREFLECTIVE SHEETING OR REFLEX REFLECTIVE MATERIAL (MANUFACTURED >6/97) (FMCSR 393.11TU): MISSING/WORN OFF
393.11TL	393.11TL	1	Ν	Ν	Ν	TRUCK-TRACTOR LOWER REAR RETROREFLECTIVE SHEETING/REFLEX REFLECTIVE MATERIAL(MANUFAC>97)(OPTIONS OF INSTALLATION:MUD FLAP/FENDER/BACK OF CAB) (FMCSR 393.11): RIGHT SIDE MISSING OVER AXLE 3
393.11LR	393.11LR	2	N	N	N	LOWER RETROREFLECT SHT/REFLEX

383.23A2 392.9A2	383.23A2 392.9A2	D 2	Y	N	N	NO TEXAS CDL - DOMICILED OVER 30 DAYS (FMCSR 383.23(a)(2)): LIVED IN TEXAS FOR 1 YER, HAS MX CDL IMPROPERLY SECURED
387.301A	387.301A	1	Ν	Ν	Ν	NO EVIDENCE OF PUBLIC LIABILITY AND PROPERTY DAMAGE INSURANCE (FMCSR 387.301(a)): DOES NOT HAVE
392.2RG	392.2RG	2	Ν	Ν	N	OPERATION OF VEHICLE WITH EXPIRED LICENSE PLATE: TRAILER REG EXPIRED 2/24
392.2RG	392.2RG	1	Ν	Ν	N	OPERATION OF VEHICLE WITH EXPIRED LICENSE PLATE: TRACTOR RED EXPIRED 6/24
396.17C	396.17C	2	Ν	N	N	NO/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)): DOES NOT HAVE
396.17C	396.17C	1	Ν	Ν	N	NO/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)): DOES NOT HAVE
392.2WC	392.2WC	2	Ν	N	N	NO/IMPROPER MUD FLAP (EXCEPTIONS: TRUCK-TRACTORS/RECREATIONAL VEHICLES/BUSES/POLE TRAILERS): LEFT 13" RIGHT 14, ALLWED 12" IN INTRASTATE COMMERCE
392.2C	392.2C	D	N	N	N	DISREGARD OFFICIAL TRAFFIC CONTROL DEVICE: DRIVER DRIVING CMV IN LEFT LANE ON IH 20 WHERE PROHIBITED BY SIG
Vio Code	<u>Section</u>		DOS Citation #		Crash	Violations Discovered MFG>11/93 (FMCSR 393.11): TRAILER LOWER COVERED IN ASPHALT/ OBSCURED

Inspection 6/4/2024


	TIFICATION								
<u>Unit Type</u> Make	Year State Pl	ate # E	quipment ID			GVWR	<u>CVSA #</u>	New CVSA #	<u>00S#</u>
1 TT PTRB	2017 TX		24		2757	52,000			
2 ST OTHR	2022 TX		T24		119	80,000			
BRAKE ADJUS	TMENTS: No Bra	ake Measuremen	ts Required Fo	or Level 2					
VIOLATIONS									
Vio Code	Section	Unit	OOS Citatio	n# Verify	Crash	Violation	s Discover	ed	
		2	N	N		ODEDAT			
392.2RG	392.2RG	2	IN	IN	Ν		PLATE: EX	HICLE WITH EX (PIRED	PIRED
392.2RG 392.2W	392.2RG 392.2W	D	N	N	N N	LICENSE OVER 34	PLATE: EX	(PIRED ANDEM AXLE:	PIRED

Inspections 17 days apart same vehicle very different results. Both inspections marked as level II inspections.

DISP ACC Yes 393.209 (d) 1 Yes U TEERING SYSTEM COMPONENT WORN/WELDED/MISSING (FMCSR 393.209(d) LOOSE PITMAN ARM AT THE GEAR BOX OUTPUT SHAFT Yes 393.45 (b) (2) 1 RAKE HOSE OR TUBING CHAFING AND/OR KINKING - CONNECTIONS TO OWER UNIT (FMCSR 393.45(b)(2)) - EMERGENCY HOSE CHAFING TO THE PLY 393.209 (b) 1 Yes VCESSIVE STEERING WHEEL LASH (FMCSR 393.209(b)) - 9 1/2 INCHES OF TEERING LASH 393.82 1 393.95 (a) 1 Image: Comparison of the planet of the			VIULA	HONS DI	SCOVE		
DISP ACC Yes 393.209 (d) 1 Yes U TEERING SYSTEM COMPONENT WORN/WELDED/MISSING (FMCSR 393.209(d) Yes U Yes 393.45 (b) (2) 1 Image: Component of the plane of the plan		(Cited FMCSR	infraction	ns are filed	in violati	on of TRC	644.151)
Yes393.209 (d)1YesUTEERING SYSTEM COMPONENT WORN/WELDED/MISSING (FMCSR 393.209(d) LOOSE PITMAN ARM AT THE GEAR BOX OUTPUT SHAFTYes393.45 (b) (2)1RAKE HOSE OR TUBING CHAFING AND/OR KINKING - CONNECTIONS TO OWER UNIT (FMCSR 393.45(b)(2)) - EMERGENCY HOSE CHAFING TO THE PLY393.209 (b)1YesUXCESSIVE STEERING WHEEL LASH (FMCSR 393.209(b)) - 9 1/2 INCHES OF TEERING LASH393.821Siga.95 (a)1IRE EXTINGUISHER VIOLATION (FMCSR 393.82) - SPEEDOMETER DOES NOT /ORK396.17 (c)1O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) UNABLE TO PROVIDE TRUCK INSPECTION REPORT 396.17 (c)O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION REPORT TRAILER	TICKET	VIOL. CITE #	Unit#	OOS	OOS	POST	
TEES IEES TEERING SYSTEM COMPONENT WORN/WELDED/MISSING (FMCSR 393.209(d)) LOOSE PITMAN ARM AT THE GEAR BOX OUTPUT SHAFT Yes 393.45 (b) (2) RAKE HOSE OR TUBING CHAFING AND/OR KINKING - CONNECTIONS TO OWER UNIT (FMCSR 393.45(b)(2)) - EMERGENCY HOSE CHAFING TO THE PLY 393.209 (b) 1 Yes U XCESSIVE STEERING WHEEL LASH (FMCSR 393.209(b)) - 9 1/2 INCHES OF TEERING LASH 393.82 1 393.95 (a) 1 IEE 393.95 (a) 1 IEE 396.17 (c) 1 IEE 396.17 (c) 2 IEE O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) UNABLE TO PROVIDE TRUCK INSPECTION REPORT 396.17 (c) 2 IEE O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) INABLE TO PROVIDE INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c))					DISP	ACC	
Yes 393.45 (b) (2) 1 Image: constraint of the system	Yes	393.209 (d)	1	Yes	U		
Yes 393.45 (b) (2) 1 Image: constraint of the system	STEERIN - LOOSE	NG SYSTEM COMP	PONENT	WORN/W		/MISSING SHAFT	(FMCSR 393.209(d))
393.209 (b) 1 Yes U XCESSIVE STEERING WHEEL LASH (FMCSR 393.209(b)) - 9 1/2 INCHES OF TEERING LASH 393.82 1 393.82 1	Yes						
393.209 (b) 1 Yes U XCESSIVE STEERING WHEEL LASH (FMCSR 393.209(b)) - 9 1/2 INCHES OF TEERING LASH 393.82 1 393.82 1	BRAKE H POWER	HOSE OR TUBING UNIT (FMCSR 393	CHAFIN .45(b)(2)	G AND/O	R KINKII GENCY	NG - CONI HOSE CH	NECTIONS TO IAFING TO THE PLY
TEERING LASH 393.82 1 EFECTIVE SPEEDOMETER (FMCSR 393.82) - SPEEDOMETER DOES NOT /ORK 393.95 (a) 1 IRE EXTINGUISHER VIOLATION (FMCSR 393.95(a)) - FORE EXTINGUISHER MPTY 396.17 (c) 1 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) UNABLE TO PROVIDE TRUCK INSPECTION REPORT 396.17 (c) 2 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION REPORT TRAILER							
EFECTIVE SPEEDOMETER (FMCSR 393.82) - SPEEDOMETER DOES NOT /ORK 393.95 (a) 1 RE EXTINGUISHER VIOLATION (FMCSR 393.95(a)) - FORE EXTINGUISHER MPTY 396.17 (c) 1 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) UNABLE TO PROVIDE TRUCK INSPECTION REPORT 396.17 (c) 2 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c))	EXCESS STEERIN	IVE STEERING WI	HEEL LA	SH (FMC	SR 393.2	209(b)) - 9	1/2 INCHES OF
/ORK 393.95 (a) 1 IRE EXTINGUISHER VIOLATION (FMCSR 393.95(a)) - FORE EXTINGUISHER MPTY 396.17 (c) 1 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) UNABLE TO PROVIDE TRUCK INSPECTION REPORT 396.17 (c) 2 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION REPORT TRAILER		393.82	1				
RE EXTINGUISHER VIOLATION (FMCSR 393.95(a)) - FORE EXTINGUISHER MPTY 396.17 (c) 1 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) UNABLE TO PROVIDE TRUCK INSPECTION REPORT 396.17 (c) 2 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) UNABLE TO PROVIDE TRUCK INSPECTION REPORT 396.17 (c) 2 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION REPORT TRAILER	DEFECT WORK	IVE SPEEDOMETE	ER (FMC	SR 393.82	2) - SPE	EDOMET	ER DOES NOT
MPTY 396.17 (c) 1 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) UNABLE TO PROVIDE TRUCK INSPECTION REPORT 396.17 (c) 2 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION REPORT TRAILER		393.95(a)	1				
O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) UNABLE TO PROVIDE TRUCK INSPECTION REPORT 396.17 (c) 2 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION REPORT TRAILER	FIRE EX ^T EMPTY	TINGUISHER VIOL	ATION (FMCSR 3	93.95(a)) - FORE	EXTINGUISHER
396.17 (c) 2 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION REPORT TRAILER		396.17(c)	1				
396.17 (c) 2 O/EXPIRED CMV INSPECTION CERTIFICATE / ANNUAL DOT (FMCSR 396.17(c)) NABLE TO PROVIDE INSPECTION REPORT TRAILER	NO/EXPI - UNABL	RED CMV INSPEC			TE / ANI N REPO	NUAL DOT	(FMCSR 396.17(c))
	NO/EXPI - INABLE	RED CMV INSPEC		ERTIFICA N REPOR	TE / ANI	NUAL DOT	(FMCSR 396.17(c))
NPROPER EXHAUST DISCHARGE (NOT REAR OF CAB) (FMCSR 393.83(e)) -		ER EXHAUST DISC ER EXHAUST LEA		E (NOT RE AMP	AR OF	CAB) (FMC	CSR 393.83(e)) -
	00S	A. Repaired	at Scen	e / Obtai	1		

Init Tune Make Veen Otate Distant				
<u>Jnit Type Make Year State Plate #</u>	Equipment ID	VIN	<u>GVWR</u> <u>CVSA #</u>	New CVSA # OOS#
1 TR KW 1996 TX	1	595	52,000	
2 FT CLEM 1986 TX	1	018	42,500	
Vio Code Section L	Unit OOS Citation #	Verify Crash	Violations Discover	ed
Vio Code Section I	Jnit OOS Citation #	Verify Crash	Violations Discover	ed

Should not have been issued a CVSA decal



Report Number: Inspection Date: 01/18/2023 Start: 11:40 AM CT End: 12:11 PM CT Inspection Level: I - Full HM Inspection Type: None	Bill of Lading: LD514621 Cargo: MOTOR VEHICLES
VEHICLE IDENTIFICATIONUnitTypeMakeYearStatePlateEquipment ID1TRCHEV 2015AZ2STBIGT 2015AZ	VIN <u>GVWR</u> 1384 40000 5317 10001
VIOLATIONS Section Type Unit OOS Citation # Verify Crash Violations Discovered 393.43 F 2 Y U N No/improper breakaway or embreakaway	nergency braking: trailer does not have required
Report Number: Inspection Date: 01/19/2023 Start: 1:20 PM CT End: 2:15 PM CT Inspection Level: I - Full HM Inspection Type: Non-Bulk	Bill of Lading: LD514621 Cargo: AUTOMOBILE/ UN1202
VEHICLE IDENTIFICATIONUnitTypeMakeYearStatePlateEquipment ID1TTCHEV 2015AZP12STBIGT 2015AZP2	VIN <u>GVWR</u> 384 13025 317 25900

VIOLATIO	NS						
Section	Type	Unit	005	Citation #	Verify	Crash	Violations Discovered
395.22H1	F	D	N		N	Ν	Driver failing to maintain ELD user's manual: Driver stated that he did not have
395.22H2	F	D	N		N	N	Driver failing to maintain ELD instruction sheet: Driver stated that he did not have
395.22H3	F	D	N		N	Ν	Driver failed to maintain instruction sheet for ELD malfunction reporting requirements: Driver stated that he did not have
395.3A3II	F	D	N		N	N	Driving beyond 8 hour driving limit since the end of the last on duty, off duty, or sleeper period of at least 30 minutes: Driving beyond 8 hour limit since end of last off duty period on 1/15/2023 all drive time after 16:07
395.8E1-PC	F	D	N		Ν	Ν	False Record of Duty Status - Improper use of Personal Conveyance Exception: 1/17/2023 driver used PC to drive from Bogart, GA to Loganville, GA the point of pickup for current load.
395.24C2III	F	D	N		Ν	Ν	Driver failed to manually add shipping document number: 1/19/2023 no BOL number listed for current load
395.24C2II	F	D	N		N	Ν	Driver failed to manually add the trailer number: 1/19/2023 trailer number listed
393.95A	F	1	N		N	N	No/discharged/unsecured fire extinguisher: New in box not mounted under rear seat
393.60D	F	1	N		N	N	Glazing permits < 70% of light: Drivers side window measured at 31% light transmission
396.3A1BOS	F	1	Y		U	N	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination: 8 total brakes on combination 4 defective equals 50%
396.17C	F	1	N		N	Ν	Operating a CMV without proof of a periodic inspection: Driver unable to provide proof of periodic inspection for truck at time of inspection
396.17C	F	2	N		Ν	N	Operating a CMV without proof of a periodic inspection: Driver stated they did not have a periodic inspection for trailer
393.48A	F	2	N		N	Ν	Inoperative/defective brakes: Axle #3 drivers side brake not working
393.48A	F	2	N		N	N	Inoperative/defective brakes: Axle #4 drivers side brake not working
393.48A	F	2	N		N	N	Inoperative/defective brakes: Axle #3 passenger side brake not working
393.48A	F	2	N		N	N	Inoperative/defective brakes: Axle #4 passenger side brake not working
393.43	F	2	Y		U	N	No/improper breakaway or emergency braking: Break-away not working when tested, trailer scaled at 12,020 lbs

		nspect Start: 1 nspect	2:11 PM	r: e: 11/16/2022 I CT End: 12:4 el: I - Full Type: None	0 PM CT		
1 TT (DENTIFIC Make Year GMC 2022 TRLR 2022	State MO	<u>Plate</u>	Equipment ID	VI	9994	<u>GVWR</u> 12100 23990

 VIOLATIONS

 Section
 Type
 Unit
 OOS
 Citation #
 Verify Crash
 Violations Discovered

 393.43
 F
 2
 Y
 U
 N
 No/improper breakaway or emergency braking: NOT CONNECTED TO TOWING VEHICLE.

	Report Number: Inspection Date: 04/05/2023 Start: 8:30 AM CT End: 9:20 AM CT Inspection Level: I - Full HM Inspection Type: None										
Unit Type 1 TR	IDENTIFIC Make Year GMC 2022 LOAD 2021	State		quipment ID	<u>VI</u>	I <u>N</u> 9994 5579	<u>GVWR</u> 12100 14000				

VIOLATIONS

Section 383.23A2	Type F	D	OOS Y	Citation #	Verify (N	N N	<u>Violations Discovered</u> Operating a CMV without a CDL: Operating a CMV without a CDL on 4/5/2023. Driver does not have a valid Class A CDL for current configuration. Missouri Class A CDL was downgraded to NON-CDL due
391.41A1-NPH	F	D	Ν		N	Ν	Operating a property-carrying vehicle without possessing a valid medical certificate - no previous history.: Medical Card shows to have expired 05/31/2021
392.8	F	D	Ν		N	N	Failing to inspect/use emergency equipment: Driver did not check / inspect emergency equipment
390.21TB	F	1	Ν		Ν	N	Carrier name and/or USDOT Number not displayed as required: USDOT number not displayed on either side of truck. Truck displays "For an and the TION" and not a sisted on MCS-150 No DBA
392.2UCR	F	1	Ν		Ν	N	Failure to pay UCR Fee: No UCR Fees located for 2023. Can be obained at WWW.UCR.GOV
396.17C	F	1	Ν		N	N	Operating a CMV without proof of a periodic inspection: No proof of inspection located on truck or provided by driver.
393.95A	F	1	N		N	N	No/discharged/unsecured fire extinguisher: No fire extinguisher located in/on truck.
393.95F	F	1	N		N	N	No / insufficient warning devices: No warning triangles / fusees / liquid burning flares
396.17C	F	2	N		N	N	Operating a CMV without proof of a periodic inspection: No proof of inspection located on trailer or provided by driver.
393.43D	F	2	Y		A	N	No or defective automatic trailer brake: Breakaway brake system not secured to towing vehicle - Secured to safety chains only.
393.130	F	2	Y		Α	N	No/improper heavy vehicle/machine securement: Bobcat T75 (Weight of 10,250 lbs.) not secured by any means. 4 tiedowns required.
393.75C	F	2	N		N	N	Tire-other tread depth less than 2/32 of inch measured in a major tread groove: Passengers side / Axle 3 - Tire has tread depth of less than 1/32" in two different locations. (Two flat spots)
393.75C	F	2	N		N	N	Tire-other tread depth less than 2/32 of inch measured in a major tread groove: Passengers side / Axle 4 - Tire has tread depth of less than 1/32" in one location (Flat Spot)

Notes: Vehicle was stopped for an inspection as I observed the Bob Cat T76 front loader sitting on the trailer with no means of securement. Driver stated that he knew the machine was not secured and that he wasn't going that far and was just being lazy today and that he knew better GVWR of both the truck and trailer located Driver looked through his files for an annual inspection for both the truck and trailer and stated that he was not able to locate one for either. Driver stated that he had just been inspected in and provided me with a copy of the inspection When going over todays inspection with the driver, he stated that never asked him about the fire extinguisher / triangles or other items listed. He said that he would have had them corrected had he known. He said that nothing on the truck had changed since the inspection. The trailer listed on the previous inspection is different than today's inspection but he said that everything should have caught the downgraded CDL since it occurred in 2021, when the else was the same. It appears that medical card expired and the inspection was in 2022. Driver was frustrated that this was not caught on previous inspection as he would have had it corrected.Driver was able to correct the OOS violations, with the exception of the CDL, while I completed the inspection report. Photos taken / CDLIS report printed and both stored locally.



(d) Safety devices in case of tow-bar failure or disconnection. Every **FULL TRAILER AND EVERY CONVERTER DOLLY** used to convert a semitrailer to a full trailer

Inspection Date: 04/12/2023 Start: 1:34 AM CT End: 2:07 AM CT Inspection Level: I - Full HM Inspection Type: None


Inspection Date: 05/23/2023 Start: 8:00 AM CT End: 9:09 AM CT Inspection Level: I - Full HM Inspection Type: Non-Bulk

VIOLATIONS: No violations were discovered

VIOLATIONS

Section	Туре		005	Citation #			Violations Discovered
395.22G	F	D	N		N	Ν	Portable ELD not mounted in a fixed position and visible to driver: Sitting on center console, In cup holder
395.22H1	F	D	N		N	Ν	Driver failing to maintain ELD user's manual: Driver admission
395.22H2	F	D	N		N	N	Driver failing to maintain ELD instruction sheet: Driver admission
395.22H3	F	D	Ν		N	Ν	Driver failed to maintain instruction sheet for ELD malfunction reporting requirements: Driver admission
395.22H4	F	D	Ν		Ν	Ν	Driver failed to maintain supply of blank drivers records of duty status graph-grids: Driver admission
391.11B2	F	D	Ν		Ν	Ν	Driver cannot read or speak the English language sufficiently to respond to official inquiries.: Driver admitted to not being able to speak English - All communication done through Google Translate
396.17C	F	1	N		N	Ν	Operating a CMV without proof of a periodic inspection: No proof of inspection located on truck or provided by driver.
393.11TU	F	1	N		Ν	N	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997: Truck missing upper corner retroreflective sheeting on both corners of the cab
393.95A	F	1	Ν		N	Ν	No/discharged/unsecured fire extinguisher: Fire extinguisher not mounted to vehicle - was new, in box, behind drivers seat.
393.9TS	F	1	N		N	Ν	Inoperative turn signal: Drivers side (left) rear turn signal INOP
393.9BRKL	AMF	1	N		N	Ν	Inoperative Brake Lamps: Drivers side (left) brake lamp INOP
393.9	F	1	N		N	Ν	Inoperable Required Lamp: Drivers side (left) rear 4-way flasher INOP / license plate illumination lamp
396.17C	F	2	Ν		N	Ν	Operating a CMV without proof of a periodic inspection: No proof of inspection located on trailer or provided by driver.
396.9D2	F	2	N		N	Ν	Failure to correct defects noted on previous inspection report: Periodic inspection as noted on previous inspection # dated 05/04/23
395.24C2I	F	D	Ν		Ν	Ν	Driver failed to manually add CMV power unit number: 05/15/23 - Driver did not add the power unit identifiers into his ELD
395.24C2II	F	D	Ν		Ν	N	Driver failed to manually add the trailer number: Driver failed to add his trailer number into his ELD on 05/15/23

395.24C2II	F	D	Ν	Ν	Ν	Driver failed to manually add the trailer number: Driver failed to add his trailer number on 05/16/23
395.24C2II	F	D	Ν	Ν	Ν	Driver failed to manually add the trailer number: Driver failed to add his trailer number on 05/17/23
395.24C2II	F	D	Ν	Ν	Ν	Driver failed to manually add the trailer number: Driver failed to add his trailer number on 05/18/23
395.24C2II	F	D	Ν	Ν	Ν	Driver failed to manually add the trailer number: Driver failed to add his trailer number on 05/19/23
395.24C2II	F	D	Ν	Ν	Ν	Driver failed to manually add the trailer number: Driver failed to add his trailer number on 05/20/23
395.24C2II	F	D	Ν	Ν	Ν	Driver failed to manually add the trailer number: Driver failed to add his trailer number on 05/21/23
395.24C2II	F	D	Ν	Ν	Ν	Driver failed to manually add the trailer number: Driver failed to add his trailer number on 05/22/23
395.24C2II	F	D	Ν	Ν	Ν	Driver failed to manually add the trailer number: Driver failed to add his trailer number on 05/23/23
395.24C2III	F	D	Ν	Ν	Ν	Driver failed to manually add shipping document number: Driver failed to enter his shipping document information on 05/22/23
395.24C2III	F	D	Ν	Ν	Ν	Driver failed to manually add shipping document number: Driver failed to enter his shipping document information on 05/23/23



VIOLATI	ONS					
Section		<u>Unit</u>	<u>005</u>	Citation #	VerifyCras	h Violations Discovered
392.2C	F	D	N		N N	Failure to obey traffic control device: Failure to obey traffic control device Fail to stop for an
395.22G	F	D	N		N N	open inspection station; SB I35 Hwy, MP 213; in violation of KSA 8-1507, 8-1910, 66-1324 Portable ELD not mounted in a fixed position and visible to driver; ELD not mounted in fixed
395.22G	F	U	IN		N N	position, visible to the driver. Was an iPad type device sitting loose, in center console under
						dash
395.22H1	F	D	N		N N	Driver failing to maintain ELD user's manual: Driver admission - Stated that he probably has
	_	_				it, but not with him.
395.22H2	F	D	N		N N	Driver failing to maintain ELD instruction sheet: Driver admission - Stated that he probably
395.22H3	F	D	Ν		N N	has it, but not with him. Driver failed to maintain instruction sheet for ELD malfunction reporting requirements: Driver
000.22110		0			N N	admission - Stated that he probably has it, but not with him.
395.22H4	F	D	N		N N	Driver failed to maintain supply of blank drivers records of duty status graph-grids: Driver
						admission - Stated that he does not have an additional paper / electronic logs should ELD go
	_	_				down.
391.11B2	F	D	N		N N	Driver cannot read or speak the English language sufficiently to respond to official inquiries.:
395.30B1	F	D	N		N N	Had to use Google Translate - Driver stated he spoke Russian and only spoke a little English Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to
555.50D1		0			IN IN	certify logs on 06/05/2023
395.30B1	F	D	N		N N	Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to
						certify logs on 06/06/2023
395.30B1	F	D	N		N N	Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to
205 2054	F	D	N		N N	certify logs on 06/07/2023 Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to
395.30B1	F	U	IN		IN IN	certify logs on 06/08/2023
395.30B1	F	D	Ν		N N	Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to
						certify logs on 06/09/2023
395.30B1	F	D	N		N N	Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to
205 2054	F	D	N		N N	certify logs on 06/10/2023 Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to
395.30B1	F	U	IN		IN IN	certify logs on 06/11/2023
396.17C	F	1	Ν		N N	Operating a CMV without proof of a periodic inspection: No proof of inspection located on
393.95A	F	1	Ν		N N	No/discharged/unsecured fire extinguisher: No fire extinguisher located in/on truck. Driver
333.33A	Г		IN		IN IN	stated that he had one in the trailer
393.95F	F	1	Ν		N N	No / insufficient warning devices: No warning triangles / fusees / liquid burning flares - Driver
						stated that he had them in the trailer
393.75B-	F	1	Y		UN	Tire-front tread depth less than 2/32 of inch on a major tread groove: Driver side front
OOS 393.75 B-	F	1	Y		UN	tire has multiple locations that measured less than 2/32"
00S	- F		T		UN	Tire-front tread depth less than 2/32 of inch on a major tread groove: Passengers side front tire - Has multiple locations that measured 0/32"
393.75C-	F	1	Y		UN	
OOS						grooves 3 separate locations 8 inches apart: Drivers side / Axle 2 - INSIDE dual -
	_					Measured 0/32" across all center tread grooves.
393.75C- OOS	F	1	Y		UN	Tire-other tread depth less than 1/32 of inch measured in 2 adjacent major tread
005						grooves 3 separate locations 8 inches apart: Drivers side / Axle 2 - OUTSIDE dual - Measured 0/32" across all center tread grooves.
393.75C-	F	1	Y		UN	Tire-other tread depth less than 1/32 of inch measured in 2 adjacent major tread
005						grooves 3 separate locations 8 inches apart: Passengers side / Axle 2 - OUTSIDE dual -
						Measured 0/32" across all center tread grooves.
393.75C- OOS	F	1	Y		UΝ	Tire-other tread depth less than 1/32 of inch measured in 2 adjacent major tread
005						grooves 3 separate locations 8 inches apart: Passengers side / Axle 2 - INSIDE dual - Measured 0/32" across all center tread grooves.
393.9T	F	1	Ν		N N	Inoperable tail lamp: BOTH tail lamps INOP at time of inspection.
396.17C	F	2	Ν		N N	Operating a CMV without proof of a periodic inspection: No proof of inspection located on
-						trailer or provided by driver.
393.75A1	F	2	Ν		N N	Tire-ply or belt material exposed: Drivers side / Axle 4 - has metal ply showing through on
202 750	-	•	N			side tread groove.
393.75C	F	2	Ν		N N	Tire-other tread depth less than 2/32 of inch measured in a major tread groove: Drivers side - Axle 5 has tread groove measured less than 2/32"
393.75C	F	2	Ν		N N	Tire-other tread depth less than 2/32 of inch measured in a major tread groove: Passengers
		-				side - Axle 4 has tread groove measured less than 2/32"

Report Number Inspection Date: 05/18/2023 Start: 2:07 PM ET End: 2:34 PM ET Inspection Level: I - Full HM Inspection Type: Bulk

Violations Discovered

Operating a property-carrying vehicle without a valid medical certificate in possession or on file with the state drivers licensing agency. History of either fail: DRIVER DOES NOT POSSESS A CDL NOR A MEDICAL CERTIFICATE

Report Number: Inspection Date: 05/22/2023 Start: 5:01 PM CT End: 5:13 PM CT Inspection Level: III - Driver/Credential HM Inspection Type: None

VIOLATIONS: No violations were discovered

S	tart: 8:13	n Date: 09 3 AM CT n Level: I ction Type		river:		
1 TT DO	DENTIFIC lake Year ODG 2023 RLR 2023	State Pla		nent ID 08 1	VIN	GVWR 0025 14000 328 12000
VIOLATIONS Section 393.95A	<u>Type Unit</u> F 1	OOS Citation N		Violations Disco No/discharged/	overed unsecured fire extingu	isher: unsecured

Star	t: 2:15 PM ection Lev	te: 09/18/2023 CT End: 4:00 vel: 1 - Full								
HM Inspection Type: Non-Bulk Driver:										
CoDriv	CoDriver:									
VEHICLE IDENTIFICATIO	VEHICLE IDENTIFICATION									
Unit Type Make Year State		Equipment ID	VIN	GVWR						
1 TT DODG 2023 NC 2 ST TRLR 2023 ME		108 1		0025 14000 328 12000						

VIOLATIONS	100	1011110	1000	100000000000000000000000000000000000000	000000	22.1.1	
Section	Type		OOS	Citation #			Violations Discovered
383.23A2	F	D	Y		N	N	Operating a CMV without a CDL: Operating a CMV without a CDL on 9/18/2023. Driver required a valid class A CDL for current configuration. Actual weight 28.080 lbs. Trailer weight 14.120 lbs.
392.2FT	F	D	N		N	N	State or International Fuel Tax (IFTA) Violation: No IFTA located for truck or carrier.
395.22G	F	D	N		N	N	Portable ELD not mounted in a fixed position and visible to driver: ELD not mounted. On tablet type device, laying loose on center arm rest, not mounted, not visible to the driver.
395.22H1	F	D	N		Ν	Ν	Driver failing to maintain ELD user's manual: Driver unable to produce ELD User Manual
395.22H2	F	D	Ν		Ν	Ν	Driver failing to maintain ELD instruction sheet: Driver unable to produce ELD Instruction Sheet
395.22H3	F	D	N		Ν	Ν	Driver failed to maintain instruction sheet for ELD malfunction reporting requirements: Driver unable to produce ELD malfunction guide
395.22H4	F	D	Ν		Ν	Ν	Driver failed to maintain supply of blank drivers records of duty status graph-grids: Driver admission - Stated that he does not have a blank record of duty status graph- grids
392.16	F	D	N		Ν	Ν	Failing to use seat belt while operating a CMV: Driver was sitting on fastened seatbelt - lap portion under him, not properly worn.
391.11B2	F	D	Ν		Ν	Ν	Driver cannot read or speak the English language sufficiently to respond to official inquiries.: Driver admission - Stated that he does not speak English. Had to use translator app (Russian)
395.30B1	F	D	Ν		Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to certify log on 09/11/2023
395.30B1	F	D	N		Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to certify log on 09/12/2023
395.30B1	F	D	Ν		Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to certify log on 09/13/2023
395.30B1	F	D	Ν		Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to certify log on 09/14/2023
395.30B1	F	D	N		Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed to certify log on 09/15/2023

395.30B1	F	D	Ν	Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed
395.30B1	F	D	Ν	Ν	Ν	to certify log on 09/16/2023 Driver failed to certify the accuracy of the information gathered by the ELD: Driver failed
395.24C2II	F	D	Ν	Ν	Ν	to certify log on 09/17/2023 Driver failed to manually add the trailer number: Driver failed to enter trailer number into
395.24C2II	F	D	Ν	Ν	Ν	ELD on 09/14/2023 Driver failed to manually add the trailer number: Driver failed to enter trailer number into
395.24C2II	F	D	Ν	Ν	Ν	ELD on 09/15/2023 Driver failed to manually add the trailer number: Driver failed to enter trailer number into ELD on 09/16/2023
395.24C2II	F	D	Ν	Ν	Ν	Driver failed to manually add the trailer number: Driver failed to enter trailer number into ELD on 09/17/2023
395.24C2II	F	D	Ν	Ν	Ν	Driver failed to manually add the trailer number: Driver failed to enter trailer number into ELD on 09/18/2023
395.24C2III	F	D	Ν	Ν	Ν	Driver failed to manually add shipping document number: Driver failed to enter shipping document into ELD on 09/14/2023
395.24C2III	F	D	Ν	Ν	Ν	Driver failed to manually add shipping document number: Driver failed to enter shipping document into ELD on 09/16/2023
395.24C2III	F	D	Ν	Ν	Ν	Driver failed to manually add shipping document number: Driver failed to enter shipping document into ELD on 09/172023
395.24C2III	F	D	Ν	Ν	Ν	Driver failed to manually add shipping document number: Driver failed to enter shipping document into ELD on 09/18/2023
395.30B1	F	С	Ν	Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Co-Driver failed to certify log on 09/11/2023
395.30B1	F	С	Ν	Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Co-Driver failed to certify log on 09/12/2023
395.30B1	F	С	Ν	Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Co-Driver failed to certify log on 09/13/2023
395.30B1	F	С	Ν	Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Co-Driver failed to certify log on 09/14/2023
395.30B1	F	С	Ν	Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Co-Driver failed to certify log on 09/15/2023
395.30B1	F	С	Ν	Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Co-Driver failed to certify log on 09/16/2023
395.30B1	F	С	Ν	Ν	Ν	Driver failed to certify the accuracy of the information gathered by the ELD: Co-Driver failed to certify log on 09/17/2023
393.11TU	F	1	Ν	Ν	Ν	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997: Truck-Tractor missing
393.11TL	F	1	N	N	N	upper body retroreflective sheeting on both sides. Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material
						requirements for vehicles manufactured after July 1997: Truck-Tractor missing lower retroreflective sheeting on both sides
393.95A	F	1	N	N	N	No/discharged/unsecured fire extinguisher: Fire extinguisher not secured to vehicle.
396.9D2	F	1	N	N	N	Failure to correct defects noted on previous inspection report: Fire extinguisher securement as noted on previous inspection dated 09/18/2023 at 0813
392.2IRP	F	1	N	N	Ν	hours. This inspection is new dispatch. IRP Apportioned Tag or Registration Violation: No IRP / Apportioned registration. No K- Trips located for carrier for current trip. Actual weight is 28,080 lbs.
396.17C	F	2	N	N	Ν	Operating a CMV without proof of a periodic inspection: No proof of inspection located on trailer or provided by driver.